

Some, FYI.
please lite, in
ADDRESS Lile.

C O V E R

FAX

To: ED SEARS/CHAS. COLLINS

Fax #: 891- 4399

Subject: 01Ly DISCHARGE

Date: 1-17-96

Pages: 3, including this cover sheet.

COMMENTS: PETROLEUM-LIKE DISCHARGE HAS

DISCHARGED IN THE PAST FROM THIS " WE AWEATHER SPRING", SOUTH OF WRAG'S 66,
IT APPEARS. Wayne LATIMER FOUND THIS

RECENTLY WHILE WORKING ON THE SOUTHERN

HILLS PROBLEM. IF you have guestions,

CALL WAYNER 864-1925.


Rund

From the desk of...

J. Randall Lyman Sewer Surveillance and Billing Supervisor Pretreatment Program 1216 W. Nichole St. Springfield, Mo. 65802

> 417-864-1467 Fax: 417-864-1918

2620 E. Sunshine 1900 5. Ventures



Public Works Department

Surveillance Enforcement and Billing Sewer Maintenance 1216 W. Nichols Springfield, MO 65802

Phone: 417/864-1923 Fax: 417/864-1918



Date:	12-5-95	Fax #: 883-2678
To:	JACK WEBSTER	
From: KAREN CHANNIER		
Message: MEMO CONCERNING GASOLINE IN THE SANITARY SEWER 5-9-95		
Pages to follow:		

NTEROFFICE MEMORANDUM

To:

FILE - 2620 E. SUNSHINE (Sunshine St. & Ventura Ave.)

CC:

From:

Gene Pabst

Date:

May 9, 1995

Subject: Gasoline in the Sanitary Sewer.

2:15 P.M.

On May 2, 1995 this Office received a call from Ebenenzer's Restaurant (2641 E. Sunshine) stating that they had a gasoline smell in their storeroom and they thought it was coming from the sanitary sewer. Karen Chandler and I went to the above location and began to check the sanitary sewer manholes in the area with our explosion meter. We checked the following manholes with these results:

2:45 P.M.

```
MH 20 Wye Map U-15
                    2-3 % L.E.L.
MH 1 Wye Map T-15
                    0-1% L.E.L.
MH 2 Wye Map T-15
                      0% L.E.L.
MH 36 Wye Map T-15
                      0 % L.E.L.
MH 21 Wye Map U-15
                      6 % L.E.L.
MH 22 Wye Map U-15
                    100 % L.E.L.
```

3:10 P.M.

We then went to Oak Grove Ave., which is downstream from the above listed manholes, and checked the following manholes:

```
0 % L.E.L.
MH 28 Wye Map U-15
MH 27 Wye Map U-15
                    0 % L.E.L.
```

3:20 P.M.

We returned to Sunshine St. and Ventura Ave. to recheck the sanitary sewer. We obtained the following results:

MH 22 Wye Map U-15 100 % L.E.L.

The sanitary sewer line, between MH 21 & MH 22, runs along the East side of Wray's 66 Service Station.

2620 E. Sunshine

We called Randy Lyman, at our office, and requested 5-6 barricades so we could open the sanitary sewer manholes to allow the gasoline to vent out. We also asked Randy to contact a Fire Marshal and Charles Collins, Missouri Department of Natural Resources, to have them meet us at Sunshine St. and Ventura Ave. Randy called us back and said that when he talked to Charles Collins, Charles stated that when Wray's 66 dug up their tanks a couple of years ago, they replaced them with used tanks and that no remediation of any kind was undertaken.

3:45 P.M.

Mike Logue, Fire Marshall, arrived at the scene. We informed him of the situation.

4:00 P.M.

Bob Corson and David Renkoski, from our office, arrived at the scene with barricades. We immediately opened MH 22, Wye Map U-15, and placed barricades around the manhole. We then checked the following manholes:

MH 21 Wye Map U-15 30 % L.E.L. (This manhole is in intersection of Sunshine & Ventura so we could not open and ventilate this manhole.)

MH 20 Wye Map U-15 5 % L.E.L. (We opened and barricaded this manhole.)

MH 2 Wye Map T-15 0 % L.E.L.

4:15 P.M.

Mike Logue, Karen Chandler and myself talked to Daryl Athens, Manager of Wray's 66, tosee if they have experienced any loss of product. He did not know of any losses. We then had him remove the covers on all of the dispensers. We only found the piping under dispenser #1 to be slightly wet from product. We then rechecked MH 22.

MH 22 Wye Map U-15 10 % L.E.L.

Charles Collins, MDNR, arrived.

4:30 P.M.

Jack Webster, owner of Wray's 66 arrived. Charles Collins removed themonitoring well covers at Wray's 66. We checked these wells with our explosion meter and obtained these results:

Monitoring Well No. 1 (East Well) 2-3 % L.E.L. Monitoring Well No. 2 (West Well) 0 % L.E.L. Karen Chandler talked to the manager of Ebenezer's and found that the gasoline smell was coming in a floor drains in their storeage room. There was no gasoline smellat this time. Karen told the manager that they should periodically put water down the drain to keep the trap in the drain working properly. Charles Collins and I went to the Clark Station at 2671 E. Sinshine, to see if they have had any product loss. The store manager was not there. We talked to the clerk, but he didn't have the information we needed. Charles Collins told the clerk to tell the manager that he would be back the next day. We looked for monitoring wells on Clark's property but apparently there are no monitoring wells at this location.

5:30 P.M.

Karen and I checked the following manholes:

```
MH 22 Wye Map U-15 8-10 % L.E.L.
MH 20 Wye Map U-15 0 % L.E.L.
```

5:45 P.M.

Karen and I checked the following manholes:

```
MH 22 Wye Map U-15 3-5 % L.E.L.
MH 27 Wye Map U-15 0 % L.E.L.
```

We left the manhole covers off manhole 20 & 22 for the evening. Charles Collins stated that he would return in the morning to do test borings along the East property line of Wray's Station. The area in question is adjacent to the City sanitary sewer. We told Charles that we would check these manholes again on the morning of May 3, 1995. We then returned to the office.

May 3, 1995

9:00 A.M.

Charles Collins called to say that they had a problem come up and that he would not be able to make it out to Wray's 66 this morning. Karen and I checked the following manholes:

```
MH 20 Wye Map U-15 0 % L.E.L.
MH 22 Wye Map U-15 0 % L.E.L.
MH 27 Wye Map U-15 0 % L.E.L.
MH 28 Wye Map U-15 0 % L.E.L.
```

We then covered MH's 22 & 20.

10:05 A.M.

MH 20 Wye Map U-15 0 % L.E.L.

MH 22 Wye Map U-15 0% L.E.L.

11:00 A.M.

Karen talked to the manager of Ebenezer's to sæ if the gasoline smell had returned. He told her that they had not smelled the gasoline since yesterday. Karen again told them about keeping water in the floor drain to prevent any type of gas from venting back into their building.

11:10 A.M.

Karen and I went to the Honda motorcyle dealership (2701 E. Sunsline) to see if maybe they had dumped a tank of gasoline down the sewer the day before. The shop foreman, Greg, stated that they never dump gasoline down the drains. They put any waste gasoline that they might have in a barrel with their waste oil and it is picked up.

11:20 A.M.

Karen and I went to AAWC National Training Center (2071-A E. Sunshine) to see if they dumped any gasoline down the sanitary sewer on May 2, 1995. They indicated that they do not have any gasoline in the building.

11:30 A.M.

Karen and I checked the following manholes:

MH 22 Wye Map U-15 0% L.E.L.

MH 27 Wye Map U-15 0% L.E.L.

Karen and I periodically checked the following MH's in the afternoon with these results:

1:22 P.M.

MH 22 Wye Map U-15 0 % L.E.L.

MH 27 Wye Map U-15 0% L.E.L.

3:20 P.M.

MH 20 Wye Map U-15 0% L.E.L.

MH 22 Wye Map U-15 0% L.E.L.

MH 27 Wye Map U-15 0% L.E.L.

May 4, 1995

Karen checked the following manholes:

8:20 A.M.

```
MH 20 Wye Map U-15 0 % L.E.L.
MH 22 Wye Map U-15 0 % L.E.L.
MH 27 Wye Map U-15 0 % L.E.L.
```

3:10 P.M.

```
MH 20 Wye Map U-15 0% L.E.L.
MH 22 Wye Map U-15 0% L.E.L.
MH 27 Wye Map U-15 0% L.E.L.
```

May 5, 1995

Karen checked the following manholes this morning:

8:25 A.M.

```
MH 20 Wye Map U-15 0 % L.E.L.
MH 22 Wye Map U-15 0 % L.E.L.
MH 27 Wye Map U-15 0 % L.E.L.
```

Karen and I checked the following manholes in the afternoon.

2:20 P.M.

```
MH 20 Wye Map U-15 0 % L.E.L.
MH 22 Wye Map U-15 0 % L.E.L.
```

May 8, 1995

Karen and I checked the following manholes in the morning:


9:00 A.M.


```
MH 20 Wye Map U-15 0 % L.E.L.
MH 22 Wye Map U-15 0 % L.E.L.
```


We will continue to periodically monitoring this situation in the future.

FROM THE DESK OF... GENE PABST WATER POLLUTION CONTROL INSPECTOR CITY OF SPRINGFIELD 1216 W. NICHOLS

Springfield, MO 65802 417-864-1488 FAX: 417-864-1918









May 9, 1995

Mr. Charles Collins Missouri Department of Natural Resources 310 E. Park Central East, Suite 500 Springfield, MO 65806

Re: Gasoline in the sanitary sewer at 2620 E. Sunshine St.

Dear Mr. Collins:

Please find the enclosed copy of our notes concerning the problem of gasoline in the sanitary sewer at 2620 E. Sunshine St., on May 2, 1995. Since we have seen no problem for several days, we are cutting back on monitoring of the area. We will, however, continue to periodically check the situation.

If you have any questions, please feel free to call at 864-1488.

Water Pollution Control Inspector Surveillance and Enforcement

CC:

Mr. Robert R. Schaefer, P.E., Superintendent of Sanitary Services.

Mr. Randy Lyman, Sewer Surveillance and Billing Supervisor.

2620 E. Sunshine